SICHE INFRASTRUCTURE SURVEY REPORT



PHASE II – ARULIGHO CAMPUS POITETE CAMPUSE

JULY 2005

Executive Summary

This report is Phase II of SICHE Infrastructure survey, an extension to survey two additional SICHE campuses, Aruligho and Poitete. Term of Reference of the survey is very much similar to the Phase I, conducting infrastructure survey of the topography where necessary replace permanent boundary marks together with the production of maps to standard scales, compilation of buildings register identifying academic and residential buildings, conduct valuation of all buildings estimating their market value, replacement cost and depreciation value and an assessment of physical and structural condition of all buildings.

Aruligho SICHE Campus is located approximately 30km west of Honiara. It has about 83 hectares of registered land area and virtually no existing infrastructure. Most facilities have been believed to be destroyed during the ethnic. The detailed survey of Aruligho SICHE campuses took seven days to complete, the final output from the survey is the production of maps plotted at standard scale of 1:3,500.

Lesson learnt from Aruligho surveys is the issues of illegal settlement, a family is currently settling inside SICHE property. Secondly is evidence that people have extract timber inside SICHE.

In land rental, SICHE currently owes Solomon Islands Government (SIG) a total of **\$698.95** in land rents since 2004. Land Lease records show SICHE as title holder to parcel number **190-072-084** with fixed term title of 75 years. To date SICHE has about **58 years** before terms of the fixed term title expires.

Poitete Campus is 43km from Gizo and 68km from Munda. Surveys took seven days to complete. A topographical map was produced a scale of 1:2,000. Lessons learnt from the survey is that currently Poitete Campus is located withing parcel number 081-003-106, and record shows that the commissioner of Lands as the title holder. SICHE management to quickly consult commissioner of Land office to sub divide parcel 081-003-106, creating a new parcel in order for SICHE to have a legal title to its Poitete campus.

Valuation of buildings was mainly conducted to Poitete Campus. 5 Academic and 11 Residential buildings, Based on valuation assessments the following figures were derived, the total market value of all SICHE building is \$508,101, total depreciation value of \$498,691 and a total replacement cost of \$940,927.

A general checklist was used to assess buildings physical and structural condition. The overall assessments indicate that most buildings general condition is satisfactory apart from signs of rust and corrosion on iron.

There is evidence that people have extract timber out the property mainly milling timber.

ı	ABLE OF CONTENTS	PAGES
1.0	TITLE	4
1.1	SCOPE OF SURVEY	4
1.2	LOCATION	
1.3	TOTAL REGISTERED LAND AREA	4
2.0	ARULIGHO SURVEY REPORT	4
2.1	TOPOGRAPHICAL SURVEY	4
2.2	LANDS SURVEY DATA	4
2.3	BUILDINGS	4
2.4	UTLITIES DATABASE	5
2.5	ARULIGHO BOUNDARY DEFINITION	5
2.6	LESSON LEARNT	
3.0	POITETE SURVEY REPORT	5
	TOPOGRAPHICAL SURVEY	5
3.2	LANDS SURVEY DATA	6
3.3	BUILDING DATABABASE	6
3.3.	1 ANALYSIS	7
	UTLITIES DATABASE	7
	KUKUM BOUNDARY DEFINITION	7
	LESSON LEARNT	7
	PLAN PRODUCTION	7
	VALUATION	8
	BUILDING PHYSICAL CONDITION	8
	ISSUES IDENTIFIED	9
	RECOMMENDATIONS	
8.0	CONCLUSIONS	13
ΔPP	ENDICES	
	HE CAMPUSES MAPS	1
	HE BOUNDARY COORDINATES LIST	2
	IE BUILDING DETAILS	3
	IE VALUATION ASSESSMENTS	4
	IE BUILDING ASSESSMENT	5
SICH	IE LAND RENTS	6
CON.	TRACTOR TERMS OF REFERENCE	7

SICHE SURVEY REPORT PHASE II

1.0 Title: Infrastructure Survey of SICHE Outer Campuses: -

- (a) Aruligho SICHE Campus
- (b) Poitete SICHE Campus

1.1 Scope of Survey

To carry out detail site surveying of Aruligho SICHE and Poitete SICHE Campuses Identifying, and re-establishing permanent boundary marks. The surveys includes identify topography and the location and size of all permanent buildings

1.3 Total Registered Land Area

No	Campus Name	Parcel Number	Land Area (Ha)
1	Aruligho	190-001-072	83На
2	Poitete	081-003-106	(1.161) Ha

2.0 ARULIGHO SURVEY REPORT

2.1 Topographical Survey

The survey of Aruligho SICHE Campus took seven days to complete. The surveying method used is GPS. Data collected from GPS was integrated with aerial photography images to form models where topography of the area is then generated.

All data collected were post processed using specialized GPS software. Mapping software (MapInfo) is also used to tabulate other needed data.

2.2 LANDS SURVEY DATA

Aruligho Campus legal boundaries and survey corner marks are kept within the Department of Lands and Survey. The coordinated of Aruligho SICHE campus was integrated in the plan, which forms the boundary layer. From the data the area of Ranadi campus is calculated.

2.3 BUILDINGS

From the surveying data collected, no SICHE building exists within the 83 hectares of land. There is however new illegal settlement in the property.

2.4 UTLITIES DATABASE

No utilities and services found in the area. Previous utilities believed to be destroyed during the ethnic tension.

2.5 ARULIGHO BOUNDARY DEFINITION

A total of seventeen (17) corner marks enclosed Aruligho SICHE campus. The northern boundary marks run along the centerline of the main and no permanent marks were placed. All other marks along the southern part of the boundary have been located using GPS and found to be in stable condition. Fence posts have already been placed over these marks therefore no marks were replaced.

2.6 LESSON LEARNT

From the survey the following lesson were learnt

- Currently there a new illegal settlement, a family settled inside SICHE property.
- There is evidence that people have extract timber out the property mainly milling timber.
- Two boundary marks on the northern border (TL4 & GP57) which indicated extend of the property need to be clearly demarcated or signs erected in order to clearly indicate SICHE boundary.

3.0 POITETE SURVEY REPORT

3.1 Topographical Survey

The survey of Poitete SICHE Campus took seven days to complete. GPS surveying method is used. Data collected from GPS was integrated with map data; this is also used to verify their features positions and accuracy.

All GPS data collected were post processed using specialized GPS software later the data is exported to a Mapping software (MapInfo) for compilation of maps output.

3.2 LANDS SURVEY DATA


The data from Lands Department is used to check Poitete SICHE boundary extends. It was found that Poitete SICHE campus has legal boundary. The campus is located within Parcel number 081-003-106, the commissioner of lands as the title holder. A temporary boundary is demarcated as shown on the maps to show extend of SICHE properties and assets.

3.3 SICHE BUILDING DATABABASE

From the survey a building list was compiled. House numbers were allocated with unique codes and class according to their type.



The building data was integrated into the Poitete surveyed data using the Building number as link. Building areas and perimeter are generated automatically using MapInfo SQL queries. The buildings are also classified and photographed. Refer to appendix 5 for complete list of buildings list.











3.3.1 Analysis

After analyzing the building list, the following results were obtained. A total of 16 buildings were found of which 5 Academic and 11 residential houses. Four of the residential buildings were currently occupied by KFPL staff.

3.5 Poitete Boundary Definition

Poitete is within Parcel 081-003-106, the commissioner of lands as the title holder of that parcel. A temporary boundary was demarcated on the map to show extent of SICHE properties and assets

3.6 LESSON LEARNT

From the survey the following lesson were learnt

- SICHE management to apply to the commissioner of lands office to further subdivide portion of parcel 081-003-106. This will give SICHE a secure land title.
- Water and Electricity are currently supplied by KFPL Company.
- Four buildings currently being occupied by KFPL staff and rented by KFPL are located outside of Poitete campus boundary.

4.0 PLAN PRODUCTION

A total of 10 maps were printed 5 copies of each.

5.1 Map Scales

Plans are plotted at standard scales. A4 versions of the plans were also done in PDF format.

 Map
 Scale

 Aruligho
 1:3,500

 Poitete
 1:2,000

4.0 Valuation

The valuation of all SICHE buildings was based on data generated from GIS. The determining factor and bases of valuation calculation is the Net Floor Area of a building. The building area generated by GIS is the building outline. Calculations therefore was done to identify Net floor area, this done by subtracting the roof overhang of a building.

Based on requirements the following valuation summaries were obtained. A complete listing of all valuation calculations can seen in Appendix 5

Table 4.0 Valuation Summaries

SICHE Campus	Market Value	Depreciation Value	Replacement Cost	Academic Buildings	Residential Buildings
Poitete	\$508,101	\$498,691	\$940,927	5	11
Aruligho	N/A	N/A	N/A	-	-
Total	\$508,101	\$498,691	\$940,927	5	11

6.0 Building Physical Condition

A checklist questionnaire form was used to assess building physical and structural conditions.

From analysis the following observations were noted

- Few Buildings have recently been renovated.
- Most have shown signs of decay and corrosions mainly on roofs
- Most buildings haven't got smoke detectors and fire alarms
- Most Academic buildings haven't got standby powers

7.0 ISSUES IDENTIFIED

The following issues were identified during the exercise:-


- Currently there an illegal settlement, a family settled inside Aruligho SICHE property.
- There is evidence that people have extract timber out the property mainly milling timber for cash
- Two boundary marks on the northern border (TL4 & GP57), indicating extend of the property needs to be clearly demarcated or signs erected in order to clearly indicate extend SICHE boundary.
- All previous SICHE building has been destroyed during the ethnic tension.
- There is no legal boundary enclosing Poitete SICHE campus. SICHE management to apply to the commissioner of lands office to further subdivide portion of parcel 081-003-106. This will give SICHE secure land title.
- Water and Electricity are currently supplied by KFPL Company. There will be issues arising with cost sharing and SICHE Management need to address it
- From valuation assessments it was found that to replace all Poitete Campus building would cost around \$940,927 including both Academic and Residential buildings.


7.1 Recommendations


- SICHE management to erect sign posts on the northern boundary (TL4 & GP57), indicating extend of SICHE property and boundary.
- There is no legal boundary enclosing Poitete SICHE campus. SICHE management to apply to the commissioner of lands office to further subdivide portion of parcel 081-003-106. This will give SICHE secure land title.


8.0 CONCLUSIONS

Overall the surveying exercise went well and tasks were completed within timeframe.









Station	Easting	Northing
MD5	581155.040	8973594.780
MD9	581331.840	8973986.960
MD59	581144.810	8973399.830
P75	581430.990	8973403.740
AKI	581829.250	8972944.790
GP55	581938.130	8973967.030
GP56	581917.010	8974230.380
GP57	581452.520	8974415.630
C29	581959.610	8973942.280
C30	581947.770	8973968.660
C31	581940.890	8973997.850
C38	581910.770	8974205.420
C39	581898.680	8974232.600
C40	581875.360	8974251.440
C41	581847.340	8974261.980
V1	581520.040	8974389.470
MDX	581487.240	8974402.180
TL4	582025.610	8973852.630
P76	581433.000	8972939.000

Poitete Buildings Description Appendix 3

No	Occupants	Bld Code	Owner	Area(m)	Perimeter(m)	Bld Type	Bld Class Description
7	SP Vazu	PC01	SICHE	65.622	35.565	RESIDENTIAL	4 Gavl Post, Timber Wall & Floor
8	Trence Titiulu	PC02	SICHE	65.622	35.565	RESIDENTIAL	4 Gavl Post, Timber Wall & Floor
5	Classrooms	PC03	SICHE	65.622	35.565	ACADEMIC	4 Gavl Post, Timber Wall & Floor
6	Office/Library	PC04	SICHE	127.889	60.236	ACADEMIC	4 Gavl Post, Timber Wall & Floor
2	Boys Domitory	PC05	SICHE	65.622	35.565	RESIDENTIAL	5 Gavl Post, Timber Wall & Floor
3	Girls Domitory	PC06	SICHE	65.622	35.565	RESIDENTIAL	5 Gavl Post, Timber Wall & Floorr
4	Dinning Hall	PC07	SICHE	128.011	59.218	ACADEMIC	4 Gavl Post, Timber Wall & Floor
1	Abilution Block	PC08	SICHE	65.622	35.565	RESIDENTIAL	6 Concrete Floor, Timber Wall
9	Under Repair	PC09	SICHE	65.622	35.565	RESIDENTIAL	5 Gavl Post, Timber Wall & Floor
10	Ben Papo	PC10	SICHE	35.702	23.903	RESIDENTIAL	7 Gavl Post, Timber Wall & Floor
12	Farm Shed	PC12	SICHE	21.262	19.283	RESIDENTIAL	8 Galv Post, Iron Roof
11	Generator House	PC11	SICHE	13.325	14.606	RESIDENTIAL	8 Concrete Floor, Timber Wall
16	Manager House	PC14	SICHE	61.176	32.395	RESIDENTIAL	4 Concrete Floor, Timber Wall
13	Staff House	FD11	SICHE	46.541	27.862	RESIDENTIAL	8 Wooden Post,TimberWall & Floor
15	Excutive House	PC15	SICHE	62.511	32.284	RESIDENTIAL	4 Concrete Floor, Timber Wall
14	Staff house	PC16	SICHE	47.006	27.973	RESIDENTIAL	8 Wooden Post,TimberWall & Floor

No	Code	Class	Туре	Occupants	Construction Details	Area (sqm)	Perimeter
					Elevated T&G flooring on galvanized iron posts with timber wall, internal		
					accomodation comprised of 3BDR with adjustable glass louvres with		
					screens and security wire mesh. Internal toilet/bathroom units with floor		
7	PC01	5	RESIDENTIAL	SP Vazu	tiles. Kitchen includes SSSink and bench. Living room with reasonable area next to the verandah.	65.622	35.565
	F 001		KESIDENTIAL	SF Vazu	Elevated T&G flooring on galvanized iron posts with timber wall, internal	03.022	33.303
					accomodation comprised of 3BDR with adjustable glass louvres with		
					screens and security wire mesh. Internal toilet/bathroom units with floor		
					tiles. Kitchen includes SSSink and bench. Living room with reasonable		
8	PC02	4	RESIDENTIAL	Trence Titiulu	area next to the verandah.	65.622	35.565
					A servants quarter with concrete foundation, skillion CI roofing and narrow		
					bedrooms. Adjoining toilet/bathroom in reasonably poor condition. An	ı	
					extension to the building comprised of external fibro cement walling and		
5	PC03	4	ACADEMIC	Classrooms	internal timber partitioned rooms. Reasonably fair condition.	65.622	35.565
					Elevated T&G flooring on galvanized iron posts with external timber wall,		
6	PC04	4	ACADEMIC	Office/Library	internal partition rooms screens and security wire mesh.	127.889	60.236
					Typical residential house with elevated T&G flooring, external timber walls,		
2	PC05	5	RESIDENTIAL	Boys Domitory	internal accomodation consists of partition bedrooms,	65.622	35.565
					Typical residential house with elevated T&G flooring, external timber walls,		
3	PC06	5	RESIDENTIAL	Girls Domitory	internal accomodation consists of partition bedrooms,	65.622	35.565
					Elevated T&G flooring on galvanized iron posts with external timber		
4	PC07	4	ACADEMIC	Dinning Hall	weatherboard walling , Timber walling	128.011	59.218
					Built of concrete block work with reinforced concrete foundation, External		
1	PC08	6	RESIDENTIAL	Abilution Block	timber walls	65.622	35.565
					Elevated T&G flooring on galvanized iron posts with timber wall, internal		
					accomodation comprised of 3BDR with adjustable glass louvres with		
					screens and security wire mesh. Internal toilet/bathroom units with floor		
	D000	_	DECIDENTIAL	Hadas Danais	tiles. Kitchen includes SSSink and bench. Living room with reasonable		25.505
9	PC09	5	RESIDENTIAL	Under Repair	area next to the verandah. Elevated T&G flooring on galvanized timber posts with external timber	65.622	35.565
					letevated 1&G flooring on galvanized timber posts with external timber		
10	PC10	7	RESIDENTIAL	Ben Papo	Timber walling	35.702	23.903
					Galvnised post with Roofing Iron		
12	PC12	8	RESIDENTIAL	Farm Shed		21.262	19.283
					Cconcrete foundation, with Exteral timber walling.		
11	PC11	8	RESIDENTIAL	Generator House		13.325	14.606
					Built of concrete block, skillion CI roofing and 3 bedrooms. Adjoining		
16	PC14	3	RESIDENTIAL	Manager House	toilet/bathroom. Verandah and good size living room	61.176	32.395
40	FD11	0	DECIDENTIAL	Stoff House	Elevated T&G flooring on galvanized timber posts with external timber		27.062
13	רוטוו	8	RESIDENTIAL	Staff House	Timber walling Built of concrete block, skillion CI roofing and 3 bedrooms. Adjoining	46.541	27.862
					Dunit of confered block, skillion of footing and 3 bedrooms. Adjoining		
15	PC15	3	RESIDENTIAL	Excutive House	toilet/bathroom. Verandah and good size living room	62.511	32.284
	DC46	_	DECIDENTIAL	04-# 1	Elevated T&G flooring on galvanized timber posts with external timber		07.070
14	PC16	8	RESIDENTIAL	Staff house	Timber walling	47.006	27.973

Valuation Schedule- Poitete Campus

Appendix 4

No	Occupants	Bld Code	Owner	Description	Bld Type	Bld Class	Net Floor Area(sq m)	Market Value	Depreciation Cost	Replacement Cost
7	SP Vazu	PC01	SICHE	Gavl Post, Timber Wall & Floor	RESIDENTIAL	4	44.283	\$ 35,869	\$ 35,205	\$ 66,425
8	Trence Titiulu	PC02	SICHE	Gavl Post, Timber Wall & Floor	RESIDENTIAL	4	44.283	\$ 35,869	\$ 35,205	\$ 66,425
5	Classrooms	PC03	SICHE	Gavl Post, Timber Wall & Floor	ACADEMIC	4	44.283	\$ 35,869	\$ 35,205	\$ 66,425
6	Office/Library	PC04	SICHE	Gavl Post, Timber Wall & Floor	ACADEMIC	4	91.747	\$ 74,315	\$ 72,939	\$ 137,621
2	Boys Domitory	PC05	SICHE	Gavl Post, Timber Wall & Floor	RESIDENTIAL	5	44.283	\$ 35,869	\$ 35,205	\$ 66,425
3	Girls Domitory	PC06	SICHE	Gavl Post, Timber Wall & Floorr	RESIDENTIAL	5	44.283	\$ 35,869	\$ 35,205	\$ 66,425
4	Dinning Hall	PC07	SICHE	Gavl Post, Timber Wall & Floor	ACADEMIC	4	92.480	\$ 74,909	\$ 73,522	\$ 138,720
1	Abilution Block	PC08	SICHE	Concrete Floor, Timber Wall	RESIDENTIAL	6	44.283	\$ 35,869	\$ 35,205	\$ 66,425
9	Under Repair	PC09	SICHE	Gavl Post, Timber Wall & Floor	RESIDENTIAL	4	44.283	\$ 35,869	\$ 35,205	\$ 66,425
10	Ben Papo	PC10	SICHE	Gavl Post, Timber Wall & Floor	RESIDENTIAL	7	21.360	\$ 17,302	\$ 16,981	\$ 32,040
12	Farm Shed	PC12	SICHE	Galv Post, Iron Roof	RESIDENTIAL	8	9.692	\$ 7,851	\$ 7,705	\$ 14,538
11	Generator House	PC11	SICHE	Concrete Floor, Timber Wall	RESIDENTIAL	8	4.562	\$ 3,695	\$ 3,626	\$ 6,842
16	Manager House	PC14	SICHE	Concrete Floor, Timber Wall	RESIDENTIAL	4	41.739	\$ 33,809	\$ 33,183	\$ 62,609
13	Staff House	FD11	SICHE	Wooden Post, Timber Wall & Floor	RESIDENTIAL	8	29.824	\$ 24,157	\$ 23,710	\$ 44,736
15	Excutive House	PC15	SICHE	Concrete Floor, Timber Wall	RESIDENTIAL	4	43.141	\$ 34,944	\$ 34,297	\$ 64,711
14	Staff house	PC16	SICHE	Wooden Post,TimberWall & Floor	RESIDENTIAL	8	30.222	\$ 24,480	\$ 24,027	\$ 45,333
	•	•		•	•	•	Total Valuations	\$ 546,547	\$ 536,425	\$ 1,012,123

Ranadi Building Assessments Appendix 5

							Space Ac	lequacy	Site Utilities				
Code	Occupants	Class	Location	FloorArea(sqm)	Replacement	C Building Type	Space	Overall Rating	Water	Site Sanitary	Electrical	Type Service	Overall
									Type Service		Service Provider		Condition
PC01	SP Vazu	4	Poitete	44.283	\$ 66,42	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC02	Trence Titiulu	4	Poitete	44.283	\$ 66,42	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC03	Classrooms	4	Poitete	44.283	\$ 66,42	5 ACADEMIC	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC04	Office/Library	4	Poitete	91.747	\$ 137,62	1 ACADEMIC	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC05	Boys Domitory	5	Poitete	44.283	\$ 66,42	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC06	Girls Domitory	5	Poitete	44.283	\$ 66,42	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC07	Dinning Hall	4	Poitete	92.480	\$ 138,72	ACADEMIC	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC08	Abilution Block	6	Poitete	44.283	\$ 66,42	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC09	Under Repair	5	Poitete	44.283	\$ 66,42	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC10	Ben Papo	7	Poitete	21.360	\$ 32,04	RESIDENTIAL	Fair	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC12	Farm Shed	8	Poitete	9.692	\$ 14,53	RESIDENTIAL	Fair	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC11	Generator House	8	Poitete	4.562	\$ 6,84	2 RESIDENTIAL	Fair	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC14	Manager House	4	Poitete	41.739	\$ 62,60	RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
FD11	Staff House	8	Poitete	29.824	\$ 44,73	6 RESIDENTIAL	Fair	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC15	Excutive House	4	Poitete	43.141	\$ 64,71	1 RESIDENTIAL	Good	Statisfactory	Utility Provided	Statisfactory	Utility Provided	Statisfactory	Statisfactory
PC16	Staff house	8	Poitete	30.222	\$ 45,33	RESIDENTIAL	Fair	Poor	Utility Provided	Poor	Utility Provided	Statisfactory	Statisfactory

Ranadi Buildings Assessment Appendix 5

			Subtructure	Evidence of Conrcern	Decay	Overall condition	Building Envelop					
				Structural Cracks	Corrosion		Material	Overall Condition of Walls	Overall Condition of Walls	Safety/Secui	Fire Escape	Windows
Code	Occupants	Class	Туре	Structural Cracks				Columns	Doors	Adequate	Overall	Overall
PC01	SP Vazu	4	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC02	Trence Titiulu	4	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC03	Classrooms	4	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC04	Office/Library	4	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC05	Boys Domitory	5	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC06	Girls Domitory	5	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC07	Dinning Hall	4	Glav Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC08	Abilution Block	6	Concrete Footing	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC09	Under Repair	5	Gav Post	No	Yes	Statisfactory	Concrete Slab	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC10	Ben Papo	7	Timber Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC12	Farm Shed	8	Gav Post	No	Yes	Statisfactory	N/A	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC11	Generator House	8	Concrete Footing	No	Yes	Statisfactory	Concrete Slab	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC14	Manager House	4	Concrete Footing	No	Yes	Statisfactory	Concrete Slab	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
FD11	Staff House	8	Timber Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC15	Excutive House	4	Concrete Footing	No	Yes	Statisfactory	Concrete Slab	Statisfactory	Statisfactory	Yes	Yes	Statisfactory
PC16	Staff house	8	Timber Post	No	Yes	Statisfactory	Wood Deck	Statisfactory	Statisfactory	Yes	Yes	Statisfactory

Ranadi Buildings Assessment Appendix 5

							Interior Elect	ical Distribution	Plumbling		Hot Water He	aters	Plumbing Fixtures	Cooling
			Condition Roofs	Interior Walls	Floor Finishes	Ceiling Conditions	Suply Meets	Overall	Pipe	Overall	Type of	overall	Toilets, Urinals	Air condition
Code	Occupants	Class	Overall	Condition	Condition	Overall	Needs	condition	Туре	condition	Fuel	Condition	Lavatories	
PC01	SP Vazu	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC02	Trence Titiulu	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC03	Classrooms	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC04	Office/Library	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC05	Boys Domitory		Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC06	Girls Domitory		Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC07	Dinning Hall	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC08	Abilution Block	(Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC09	Under Repair		Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC10	Ben Papo	7	7 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC12	Farm Shed	8	Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC11	Generator House		Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC14	Manager House	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	Natural Gas	Statisfactory	Statisfactory	Statisfactor
FD11	Staff House	8	Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Statisfactory	N/A
PC15	Excutive House	4	1 Statisfactory	Statisfactory	Hard Flooring	Statisfactory	Yes	Statisfactory	PVC	Statisfactory	Natural Gas	Statisfactory	Statisfactory	N/A
PC16	Staff house	3	3 Statisfactory			Statisfactory	Yes	Statisfactory	PVC	Statisfactory	N/A	N/A	Poor	N/A

Ranadi Building Assessment Appendix 5

				Fire Alarm				Environment/Con	nfort	
			Air Ventilation	Systems	Smoke	Emergency	Stanby	General		Leak in roofs
Code	Occupants	Class			Detectors	Lighting	Power	Appearance	Visible Leaks	
PC01	SP Vazu	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC02	Trence Titiulu	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC03	Classrooms	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC04	Office/Library	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC05	Boys Domitory	5	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC06	Girls Domitory	5	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC07	Dinning Hall	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC08	Abilution Block	6	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	Yes
PC09	Under Repair	5	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
PC10	Ben Papo	7	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
PC12	Farm Shed	8	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
PC11	Generator House	8	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
PC14	Manager House	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
FD11	Staff House	8	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
PC15	Excutive House	4	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No
PC16	Staff house	8	Statisfactory	N/A	N/A	Statisfactory	N/A	Good	Yes	No



Fax (677) 20094

FROM:

Commissioner Of Lands

LANDS DIVISION

Ministry of Lands P.O.Box G38 Honiara Solomon Islands

Date: 14 June 2005

TO:

SICHE

P.O. Box G23

Honiara

Client Number: 3101

Re: Cap 93, LTA Schedule 125 - Rent

As the holder of the under listed estates, our records reveal that you owe the Government the sum(s) set out below, being the annual rent plus compounded interest of 8% per annum on those estates up to and including 1/01/2005. For your conveniance the list shows the debt to each estate.

Should you spot any errors in our assessment, you may bring it to the attention of this office with supporting receipts and documents.

This debt must be settled now, as this is the last and only notice to be served.

Thank you.

Commissioner of Lands

Parcel:	Year:	Rent Due:	Interest Due:	Total Due For Year:
190-001-072	1993	\$35.00	\$46.60	\$81.60
190-001-072	1994	\$35.00	\$40.55	\$75.55
190-001-072	1995	\$35.00	\$34.95	\$69.95
190-001-072	1996	\$35.00	\$29.75	\$64.75
190-001-072	1997	\$35.00	\$24.95	\$59.95
190-001-072	1998	\$35.00	\$20.50	\$55.50
190-001-072	1999	\$35.00	\$16.40	\$51.40
190-001-072	2000	\$35.00	\$12.60	\$47.60
190-001-072	2001	\$35.00	\$9.05	\$44.05
190-001-072	2002	\$35.00	\$5.80	\$40.80
190-001-072	2003	\$35.00	\$2.80	\$37.80
190-001-072	2004	\$35.00	\$0.00	\$35.00
190-001-072	2005	\$35.00	\$0.00	\$35.00
192-007-031	1989	\$2,000.00	\$4,344.30	\$6,344.30
192-007-031	1990	\$2,000.00	\$3,874.35	\$5,874.35
192-007-031	1991	\$2,000.00	\$3,439.25	\$5,439.25
192-007-031	1992	\$2,000.00	\$3,036.30	\$5,036.30
192-007-031	1993	\$2,000.00	\$2,663.25	\$4,663.25
192-007-031	1994	\$2,000.00	\$2,317.85	\$4,317.85
192-007-031	1995	\$2,000.00	\$1,998.00	\$3,998.00
192-007-031	1996	\$2,000.00	\$1,701.85	\$3,701.85
192-007-031	1997	\$2,000.00	\$1,427.65	\$3,427.65

Page 1 of 2

OFFICE USE ONLY

Rent	Interest	Total	Receipt
-100			
Date		Signature	